



## Assignment

Client

We Buy Cars

## Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registration Number	675513144
Manufacturer	MERCEDES-BENZ		
Model	C CLASS SEDAN	Paint Finish	C - COMMON
VIN	WDD2040082R088866	Fuel	DIESEL
Year Model	2009	Transmission	AUTOMATIC
Km Reading	238,574 KM	Doors	4
Cab / Body Type	SEDAN	Color	SILVER

## General Condition

### Interior

Components	Condition	Inspection Result
Interior	As Expected	The interior normal for age and mileage of the vehicle.
Seats	As Expected	The seats show minor signs of wear and/or discoloration / fading / stains.
Interior trim, roof lining, carpet	As Expected	Interior trim and/or roof lining and/or carpets show normal signs of wear and/or minor staining.
Dashboard / Cluster	As Expected	The dashboard and cluster shows normal signs of wear.
Heating, ventilation	Very Good	The functions of heating and ventilation are without detectable defects.
Interior control units (windows, mechanical sunroof, etc.) / instrument cluster	Very Good	The function of control units and/or instrument cluster is without detectable faults.
Air-condition	Very Good	The testable functions of the air condition is without deficiencies.
Electric windows	Very Good	The function of the electric windows is in working order.
Electric sunroof or electric roof	Very Good	The function of electric sunroof and/or electric soft top is in working order.
Electrically adjustable seats and / or seat heaters	Very Good	The functions of the electrically adjustable seats and/or seat heaters are in working order.

### Exterior

Components	Condition	Inspection Result
Rims	As Expected	The rims are as expected according to age and mileage.
Mechanical function of doors / bonnet / tailgate	Very Good	The mechanics of doors / bonnet / tailgate are in working order.
Vehicle Body	As Expected	The condition of the vehicle body is as expected according to age and mileage and may include minor dents/scratches/ signs of repair work/ corrosion.
Windows	As Expected	The glass panes have stone chips and/or scratches.
Hang-on parts (grill, bumpers, mirrors, antennas, strips, etc.)	As Expected	Hang-on parts (grill, bumpers, mirrors, antennas, strips, etc.) show normal wear and/or minor damages according to age and mileage.
Spare wheel	Poor	The spare wheel tread depth is below 1mm, damaged or missing and must be replaced.
Tires	Poor	One or more tires are not in roadworthy condition and need to be replaced.

## Engine, Gearbox, Drivetrain

Components	Condition	Inspection Result
Engine-Oil	Very Good	The engine-oil level is normal with no visible signs of contamination.
Engine Cooling System	Very Good	The cooling system is without testable defects. The coolant level is normal.
Oil loss engine	Very Good	The engine is without visible oil leak.
Oil loss gearbox, drive shaft	Very Good	The gearbox and/or drive shafts are without visible oil loss.
Exhaust System	As Expected	The exhaust system shows signs of damages and/or rust, the functionality is not affected.
Gearshift, clutch, automatic transmissions (road test)	Very Good	During the road test no deficiencies were detected on gearshift, clutch, automatic transmissions.
Noise Levels Engine	Poor	During the road test atypical noises were detected. This may impact the performance of the vehicle and result in mechanical failure if not attended to.
Noise Levels Transmissions	Very Good	During the road test no atypical noises were detected.
Noise Levels Axles	Very Good	During the road test no atypical noises were detected.
Engine	As Expected	Minor deficiencies were detected - the function is not affected, but repairs may be needed in the near future.
Gearbox	Very Good	No defects were detected.
Drivetrain	Very Good	No defects were detected.

## Axles, Undercarriage

Components	Condition	Inspection Result
Brake Fluid	Very Good	The brake fluid level is normal with no visible signs of contamination.
Brakes	As Expected	The brake pads and / or discs show signs of wear and may need replacement in the near future.
Brake System	Very Good	The brake system in good condition.
Vehicle undercarriage	Poor	The undercarriage has major impact and/ or corrosion damages and/or signs of non-quality repair. The undercarriage need to be repaired to be deemed safe for future use.
Axles , Suspension	Poor	Axles and / or suspension show damages that affect the safety of the vehicle and will need repairs to be deemed safe for future use.

## Brakes

### Brake Test Results

	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
Front	3.38	3.46	-	
Rear	2.74	2.79	-	
Emergency / Parking	2.44	1.66	-	

## Tyres and Rims

### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/45R17	91W	Continental	Contact	V	1514	1 mm
Front Right	225/45R17	91W	Continental	Contact	V	2914	0 mm
Rear Left	245/45R17	91W	Continental	Contact	V	3314	2 mm
Rear Right	245/40R17	91W	Continental	Contact	V	3314	2 mm
Spare	225/45R17	91W	Continental	Contact	V	0000	0 mm

\* Tyre Legend: V=Virgin, R=Recap

Tyre tread depth minimum 1mm according to National Road Traffic Act 93 of 1996.

## Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufactures).

## Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE. NORMAL WEAR AND TEAR MARKS ON BODY , INTERIOR AND MECHANICAL PARTS

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Angelino Church

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

## Damages

Damage	Repair Way
Tyre Front Right Smooth	Roadworthy Relevant
Both front stabilizer dust covers torn	Roadworthy relevant
Both front lower control arms bushes cut torn	Roadworthy relevant



Spare wheel



Oil cap




Coolant level



Chassis



Left front stabilizer dust cov



Right front stabilizer dust co




Left front lower control arm b




Right front lower control Arm




Dekra sticker



Shocks and brakes report



Diagnostic report



Diagnostic report



[illegible]

## Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT




90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD





RR TYRE TREAD



RF TYRE TREAD



VIN PLATE OR STICKER



ENGINE 1



CHASSIS



ENGINE 2





Tyre Front Right