

Lecture 7 - Fracture Toughness

Dr. Nicholas Smith

Wichita State University, Department of Aerospace Engineering

February 22, 2021

1

schedule

- 22 Feb - Fracture Toughness
- 24 Feb - Fracture Toughness, HW3 Due, HW 2 Self-grade due
- 1 Mar - Residual Strength
- 3 Mar - Residual Strength, HW4 Due, HW 3 Self-grade due

2

- fracture toughness
- plain strain
- plain stress

fracture toughness

fracture toughness

- The critical load at which a cracked specimen fails produces a critical stress intensity factor
- The “critical stress intensity factor” is known as K_I
- For Mode I, this is called K_{Ic}
- The critical stress intensity factor is also known as fracture toughness

$$K_{Ic} = \sigma_c \sqrt{\pi a} \beta$$

- Note: “Fracture Toughness” can also refer to G_{Ic} , which is analogous to K_{Ic} , but not the same


4

fracture toughness

- Fracture toughness is a material property, but it is only well-defined in certain conditions
- Brittle materials
- Plane strain (smaller plastic zone)
- In these cases ASTM E399-12 is used.

5

fracture toughness



6

unstable cracks

- Stable crack growth means the crack extends only with increased load
- Unstable crack growth means the crack will continue to extend indefinitely under the same load
- For a perfectly brittle material, there is no stable crack growth, as soon as a critical load is reached, the crack will extend indefinitely

7

stable cracks

- For an elastic-plastic material, once the load is large enough to extend the crack, it will extend slightly
- The load must be continually increased until a critical value causes unstable crack growth


8

fracture toughness

- During an experiment, we will record the crack length and applied load (P_i , a_i) each time we increase the load
- We can calculate a unique stress intensity factor K_{Ii} at each of these points
- These are then used to create a “K-curve”, plotting K_I vs. a

9

K-curve



10

K-curve

- Materials will generally not be as flat as the perfectly brittle example
- Plane strain conditions and brittle materials will tend towards a “flat” K-curve
- K_{IC} for brittle/plane strain is very well defined
- KC for plane stress can refer to two things
- Either the maximum KC during a test, or tangent point on KR -curve (R-curve)

11

example

- In composites, and adhesives, some work is needed to ensure stable crack growth
- The Double-Cantilever Beam (DCB) experiment to find G/C illustrates this

$$C = \frac{\delta}{P}$$

$$C = \frac{2a^3}{3EI}$$

$$G = \frac{P^2}{2b} \frac{dC}{da}$$

$$G = \frac{P^2 a^2}{bEI}$$

12

example

- For crack growth to be stable we need

$$\frac{dG}{da} \leq 0$$

- Under fixed-load conditions, we find

$$\frac{dG}{da} = \frac{2P^2 a}{bEI}$$

- This is always positive, and thus results in unstable crack growth

13

- Under fixed-displacement conditions, we substitute for P
- We find

$$\frac{dG}{da} = -\frac{9\delta^2 EI}{ba^3}$$

- Which is always stable, so for DCB tests, displacement control is generally used

plane strain, brittle

- For relatively brittle materials, we don't need to worry about the R-curve
- Specimens are made according to these specifications

$$a \geq 2.5 \left(\frac{K_{IC}}{\sigma_{YS}} \right)^2$$

$$b \geq 2.5 \left(\frac{K_{IC}}{\sigma_{YS}} \right)^2$$


$$W \geq 5 \left(\frac{K_{IC}}{\sigma_{YS}} \right)^2$$

15

ASTM E399

1. Select specimen size
2. Select specimen type (Compact Tension or Single Edge Notched Bend)

16



17





FIG. A3.1 Bend SE(B) Specimen—Standard Proportions and Tolerances



19

Machine specimen

Fatigue crack specimen $K_f < 0.6K_{IC}$

This is to ensure that the plastic zone size during fatigue is smaller than the plastic zone size during testing

If K_{IC} has not yet been determined, you may have to guess the first time

20


Mount specimen, attach gage

Load rate should ensure “static” load conditions. (30 - 150 ksi $\sqrt{\text{in.}}$ /min.)

Determine the “provisional” value of KIC (known as KQ)

21

ASTM E399



22

- If the load-displacement curve is like the first figure, with some non-linearity, we let P_Q be the point of intersection between the load-displacement curve and a line whose slope is 5% lower than the slope in the elastic region
- “Pop-in” occurs when there is stable crack extension before the plasticity begins. We let P_Q be the point where stable crack extension begins.

23

ASTM E399

- For a perfectly linear material, $P_Q = P_{max}$.

$$K_Q = \frac{P_Q}{BW^{1/2}} f\left(\frac{a}{W}\right) \quad \text{Compact Tension}$$

$$K_Q = \frac{P_Q}{BW^{3/2}} g\left(\frac{a}{W}\right) \quad \text{SENB}$$

24

Ensure that your specimen is still valid

$$a \geq 2.5 \left(\frac{K_Q}{\sigma_{YS}} \right)^2$$

$$b \geq 2.5 \left(\frac{K_Q}{\sigma_{YS}} \right)^2$$

$$W \geq 5 \left(\frac{K_Q}{\sigma_{YS}} \right)^2$$

25

ASTM E399

- For stable crack extension, check the P_{max}

$$\frac{P_{max}}{P_Q} \leq 1.10$$

- Check for symmetric crack front, a_1 , a_2 , and a_3 must be within 5% of a . a_s must be within 10% of a .

$$\frac{a_1 + a_2 + a_3}{3} = a$$

- Load-displacement should have an initial slope between 0.7 and 1.5

26

plane stress, ductile

R-curve

- For materials with some plasticity, the *KR* Curve, or R Curve, is very important
- Sometimes called a “resistance curve” it is generally dependent on
 - Thickness
 - Temperature
 - Strain rate

- When done correctly, KR curves are not dependent on initial crack size or the specimen type used
- ASTM E561 describes a general procedure

28

ASTM E561

- Compact Tension (CT or C(T)) specimens may be used for plane stress KR curves
- The other specimen which is permitted is a middle-cracked tension specimen (M(T))
- M(T) specimens are preferred in many cases due to a more uniform stress distribution (particularly important for anisotropic materials)

29




Figure 1: An image showing how long cracks are allowed to be relative to the center hole in middle-cracked tension specimens

#13 Drill

30

minimum sample dimensions

Table of Minimum M(T) Specimen Geometry for Given Conditions							
K_{Rmax}/σ_{YS} \sqrt{m}	$\sqrt{in.}$	Width		$2a_0$		Length ^A	
		m	in.	m	in.	m	in.
0.08	0.5	0.076	3.0	0.025	1.0	0.229	9
0.16	1.0	0.152	6.0	0.051	2.0	0.457	18
0.24	1.5	0.305	12.0	0.102	4.0	0.914	36
0.32	2.0	0.508	20.0	0.170	6.7	0.762	30
0.48	3.0	1.219	48.0	0.406	16.0	1.829	72

Figure 3: A table of minimum recommended specimen dimensions for middle-cracked tension specimens.

31

minimum sample dimensions

Table of Minimum C(T) Specimen Width W for Given Conditions, m (in.)

K_{Rmax}/σ_{YS}		Maximum a_p/W				
\sqrt{m}	$\sqrt{in.}$	0.4	0.5	0.6	0.7	0.8
0.10	0.6	0.02 (0.8)	0.03 (1.0)	0.03 (1.3)	0.04 (1.7)	0.06 (2.5)
0.20	1.3	0.08 (3.3)	0.10 (4.0)	0.13 (5.0)	0.17 (6.7)	0.25 (10.0)
0.30	1.9	0.19 (7.5)	0.23 (9.0)	0.29 (11.3)	0.38 (15.0)	0.57 (22.6)
0.40	2.5	0.34 (13.3)	0.40 (15.9)	0.51 (19.9)	0.67 (26.5)	1.01 (39.8)
0.50	3.1	0.53 (20.9)	0.64 (25.1)	0.80 (31.3)	1.06 (41.8)	1.59 (62.7)


Figure 4: A table of minimum recommended specimen dimensions for compact tension specimens.

32

effective crack length

- ASTM E561 describes three ways to obtain the effective crack length during testing
 1. Measure the crack length visually and calculate r_p
 2. Measure crack length using “unloading compliance” and adding plastic zone size
 3. Measure the effective crack size directly using “secant compliance”

33



34

secant compliance $M(T)$

- Using the slope data from our load-displacement curve, we can calculate the effective crack length using

$$EB \left(\frac{\Delta v}{\Delta P} \right) = \frac{2Y}{W} \sqrt{\frac{\pi a/W}{\sin(\pi a/W)}}$$

$$\left[\frac{2W}{\pi Y} \cosh^{-1} \left(\frac{\cosh(\pi Y/W)}{\cos(\pi a/W)} \right) - \frac{1 + \nu}{\sqrt{1 + \left(\frac{\sin(\pi a/W)}{\sinh(\pi Y/W)} \right)^2}} + \nu \right]$$

35

secant compliance $M(T)$

- This equation is difficult to solve directly for a (for $M(T)$ specimens)
- Instead it is generally solved iteratively
- The following equations are used to give a good initial guess to use in iterations

36

secant compliance $M(T)$

$$X = 1 - \exp \left[\frac{-\sqrt{[EB(\Delta v / \Delta P)]^2 - (2Y/W)^2}}{2.141} \right]$$
$$\frac{2a}{W} = 1.2235X - 0.699032X^2 + 3.25584X^3 - 6.65042X^4 + 5.54X^5 - 1.66989X^6$$

37

secant compliance $M(T)$

In the above equations, the following are the definitions of parameters used

$E =$	Young's Modulus
$\Delta v / \Delta P =$	specimen compliance
$B =$	specimen thickness
$W =$	specimen width
$Y =$	half span
$a =$	effective crack length
$\nu =$	Poisson's ratio

38

secant compliance $C(T)$


- For $C(T)$ specimens, we use the following equations

$$EB \frac{\Delta v}{\Delta P} = A_0 + A_1 \left(\frac{a}{W} \right) + A_2 \left(\frac{a}{W} \right)^2 + A_3 \left(\frac{a}{W} \right)^3 + A_4 \left(\frac{a}{W} \right)^4$$

- The coefficients will differ based on where the displacement is measured from

39

secant compliance $C(T)$



40

secant compliance $C(T)$

loc	A0	A1	A2	A3	A4
V0	120.7	-1065.3	4098.0	-6688.0	4450.5
V1	103.8	-930.4	3610.0	-5930.5	3979.0

41

secant compliance C(T)

loc	C0	C1	C2	C3	C4	C5
V0	1.0010	-4.6695	18.460	-236.82	1214.90	-2143.6
V1	1.0008	-4.4473	15.400	-180.55	870.92	-1411.3

42

secant compliance C(T)

- Where the initial guess for a is provided by

$$\frac{a}{W} = C_0 + C_1 U + C_2 U^2 + C_3 U^3 + C_4 U^4 + C_5 U^5$$


- and U is given by

$$U = \frac{1}{1 + \sqrt{EB \frac{\Delta v}{\Delta P}}}$$

43

- If the test is stopped and re-started frequently (to measure crack length by hand or to use the compliance method of crack measurement) buckling can interfere with results

44



45

- If buckling is shown to be present in the test, supports can be used to prevent buckling
- These supports can introduce friction
- They should be well-lubricated for accurate test results

net section stress


- One final consideration when dealing with plane stress fracture mechanics is the net section stress
- For the test to be valid, failure must occur due to fracture, not general static failure
- Static failure will occur when $\sigma_N = \sigma_{YS}$

- Once the effective crack length and KI_e has been determined for the test, we can generate the KR curve
- The KR curve is quite simply a plot of KI_e vs. a for the test performed (i.e. with varying stress and increasing crack length)

initial crack length


- When the test is performed correctly, the KR curve is not a function of the initial crack length
- For this reason, we often plot KI_e vs. Δa , to subtract the initial crack length
- We can superpose constant-stress K -curves on this graph, the curve which intersects at a tangent point creates the most “standard” definition for KC

example



50

example



51