



REPORT

PROLINTAS Smart Surveillance System

Highway: LKSA



From: 23/08/2020 6:00 AM

To: 23/08/2020 2:00 PM

Generated At: 24/08/2020



DETECTION SUMMARY

	6		
Highway	Total Detection Count	Report Date 24/08/2020	Report auto generated
0 ACCIDENT	2 FOREIGN OBJECT	2 ASSET DAMAGE	2 POTHOLE
0 SURFACE CRACK	0 WATER PONDING	0 LIQUID SPILLAGE	0 ANIMAL
0 SLOPE FAILURE			

DETECTION OVERVIEW

No.	ID	Detection Type	Description	Location	Vehicle
1	49	Foreign Object		KM 3	
2	50	Asset Damage		KM 3	
3	51	Pothole		KM 3	
4	52	Foreign Object		KM 3	
5	53	Asset Damage		KM 3	
6	54	Pothole		KM 3	

FOREIGN OBJECT



ID : 49	
Description	
Date	2020/07/01
Time	1:36 AM
Location	KM 3
Vehicle	



ID : 52	
Description	
Date	2020/07/01
Time	1:36 AM
Location	KM 3
Vehicle	

