




TODD:
TEST IF R9 FIXES THE "ALWAYS TO ISP AFTER RESET" ISSUE
BY SOLDERING A 10K PULL-UP



Pressing SWx while powering Interface:
N_RESET_FB_BL - mbed bootloader
N_RESET_FB_ISP - ROM MSC bootloader

