



Predicting Water Well Conditions

Nina Vergara


Extraction Mechanism




Management Group



Construction Year



Quality



In Summary

- Quality: Functional Needs Repair
- Construction Year: Non-Functional & Functional
- Management Group: All Conditions
- Extraction Mechanisms: Non-Functional