


TECHNICAL TOPICS

POWERTRAIN



<h3>Spark Plug Inspection</h3>	<p>2016-2022 Range Rover, Range Rover Sport, Velar, Evoque, Discovery, Discovery Sport, Defender, XE, XF, XJ, F-Pace, F-Type, E-Pace fitted with Petrol Engines</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> Customer States engine runs rough with MIL illuminated <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> Spark plug damage is found during diagnosis Vehicle repair history shows mechanical repairs having been performed previously <p><u>Status:</u></p> <ul style="list-style-type: none"> Damage to spark plugs may occur due to detonation caused by previous engine component failure. This may also occur as a result of high combustion temperatures Follow the guidelines under TOPIx workshop manuals for faults that may request inspection of the spark plugs Failure to inspect the spark plugs during the initial repair may cause a repeat visit, and additional engine damage. <p>Refer to TOPIx workshop manual 100-00: General Information for repair guidelines</p>	



PRINTED COPIES ARE UNCONTROLLED