





MPD UPDATE


Electrical



No Audio Output due to F1A5 Polar Switch		16MY – 20MY RR Velar, RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF & XJ equipped with InControl Touch Pro	
<p><u>Problem Description:</u></p> <ul style="list-style-type: none">- Customer may state there is no audio present or volume control. <p><u>Current Status:</u></p> <ul style="list-style-type: none">- IMC hardware was faulty causing a missing F1A5 Polar Switch.- Part stock has been confirmed clean. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none">- LR – SSM 74491 has been released on July 26th 2019- JAG – SSM 74490 has been released on July 26th 2019			
KPI's			
Total VIN Count	Status	Issue Owner	
		NAS: George Krzyzanowski	

 Solution Unavailable or project not yet accepted

 Solution known, not yet delivered

 Service Fix Available, Communication Published

