





MPD UPDATE


Electrical



Quiescent Drain after State Inspection		19MY – 20MY RR Velar, RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF & XJ	
<p><u>Problem Description:</u></p> <ul style="list-style-type: none">- Customer states not able to start vehicle after state inspection test is performed. <p><u>Current Status:</u></p> <ul style="list-style-type: none">- Project is being analyzed by local & UK Engineering. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none">- Please submit an EPQR if you encounter this scenario.			
KPI's			
Total VIN Count	Status	Issue Owner	
		NAS: George Krzyzanowski	

 Solution Unavailable or project not yet accepted

 Solution known, not yet delivered

 Service Fix Available, Communication Published

