



TODO R2 will be causing trouble due to 1k pull-up with LED on CNC side
 - replace R2 with 470R