

GOLDEN KEY WIRING PLAN

GAP means put a break in the track here with an insulated joiner. The ones with arrows mean you should put it in the position where you want the isolated siding to start. Others just need to go roughly half way between the points, the position is not critical.

FROG means solder the thin YELLOW wire labelled "FROG" from the points motor to the track here.

FEED means a track power feed from the controller. These will be thin RED and BLACK wires with labels that match this plan.