

## **Short keys to be used after pressing space bar while drawing layout**

Space + m = To draw metal layer  
+ pp = via  
+ pc = poly contact  
+ pr = power rails  
+ p = poly  
+nwc= n-well contact  
+pwc= p-well contact

## **Some shortcuts to be used independently**

d = to delete  
F2= to unselect  
u = to undo  
c = to copy  
m= to move

## **Commands to be used on console for getting into layout window**

(Pyxis-MentorGraphics)

```
$ csh  
$ source mentor.cshrc  
$ adk_dve <folder name> -t tsmc018 (to create environment)  
$ adk_ic &
```

## **Unix Tricks and Tips for new users**

[https://drive.google.com/open?id=0B7U\\_cyggvAVBR1hPUXd5Q2hGYWM](https://drive.google.com/open?id=0B7U_cyggvAVBR1hPUXd5Q2hGYWM)