


Approved By: 	Implementation Date: 30 OCT 2021	Issued By: NA
Sign & Date: 30.10.2021	Sign & Date: 30.10.2021	Sign & Date: NA

**Cipla**  
Goa, Unit-VII

### AIR FLOW VISUALIZATION TEST RECORD

Department: ~~Coat~~ Coating

Type of test: Air flow visualization

Media used for the test Method: Clean viewer/ Dry ice/Clean room fogger/ Fibre tracer thread or Thin film tape /

Glycol fogger/ Mini colt 4 smoke generator/ FPT 500 flow pattern tester/ Fog machine.

Test condition: At Rest

State of occupancy: At built (At static) In dynamic

Apparatus used: video camera

CD/DVD Number: GOA-09/COAT/AHU-MDL-123/23/VT-11

Differential pressure shall be within limits: found within limit.

Plan for air flow visualization:

Number of supply grills as per layout to be verified: 06 Nos.

Number of return grills as per layout to be verified: 07 Nos.

Number of door openings to be checked: 01 Nos.

Verified by: Sm 21.01.23 (Sign/Date)

Verified by: Sm 21.01.23 (Sign/Date)

Verified by: Sm 21.01.23 (Sign/Date)

Sr. No.	Name of the area	Room No.	Equipment name	Equipment code	Videography completes all supply/return/door openings (Yes/No)	Reference CD/DVD number with CD/DVD received date	Observation / Remark	Summary of findings of air flow pattern	Area cleaning status	Study reviewed by Engg dept. Name / Sign/Date	Study approved by QA dept. Name / Sign/Date
01	Inpro cess-Tv	7210	Air handling unit	MDL-123	yes	GOA-07/COAT/AHU-MDL-123/23/VT-11 23.01.2023	found satisfactory	Smoke found diffusing uniformly from supply grill into room and returning from return grill	cleaned	Suraj M <u>Sm</u> 16.02.2023	<u>Am</u> 12.05.2023
					na						

Prepared By:  
Sign/Date:

Sm  
29.10.2021

Sm  
16.02.2023

\* wrong Endry Connected Sm 21.01.2023

\* Sm  
21.01.2023