


DIGITAL SERVO AMP JUMPER SETTINGS

SHOT CONTROL AMP 1		PRESSURE AMP 2	
J1A	OUT	J2A	IN
J1B	OUT	J2B	IN
J1C	OUT	J2C	OUT
J1D	IN	J2D	OUT
J1E	OUT	J2E	IN
J1F	OUT	J2F	OUT
J1G	OUT	J2G	IN
J1H	OUT	J2H	OUT
J1I	IN	J2I	OUT
J1J	IN	J2J	OUT
J5A	OUT	J4A	OUT
J5B	OUT	J4B	IN
J5C	OUT	J4C	OUT
J5D	OUT	J4D	OUT
J6	OUT	J7	OUT



DIGITAL GAIN POT 2 MUST BE SET TO 127 IN THE F4 VALVE TEST SCREEN. OFFSET VOLTAGE MUST BE SET TO ZERO IN THE F2 SET DAC SCREEN.

DETAIL A
PRESSURE CONTROL SERVOVALVE
(OPTIONAL)



DETAIL B

VIATRAN PRESSURE TRANSDUCER
W/MATING CONNECTOR
VISI-TRAK PN: M56-06346



DETAIL C

SENSOR CONVERTER PCB
W/VISI-TRAK SENSOR
VISI-TRAK PN: MVD-07014

DRY CONTACT
CUSTOMER SUPPLIED

FUSES: LITTLEFUSE 5MMx20MM
0.5A FAST ACTING #217.500 (TB1-4 THRU TB1-9)

FUSES: LITTLEFUSE .25x1.25
.1A FAST ACTING #213.100 (TB1-42, TB1-43, TB1-52, TB1-53)