

## Copying the Display Files to the Office Workstation


If you have not already done so at the Office Workstation, pull down the "File" menu and choose "Passwords". On the password screen press the "Edit Options" button. This will bring up the following screen.

Check the "Use Part Based Corner Parameters and Trend Chart Setups" checkbox as shown and then save your changes.


The display setup files will now be saved in sub directories in the "c:\v5\display" directory. The name of each sub-directory is the name of the machine. These directories will not be created until you save the display setup for a part on each machine. You can also create the directories manually.



If you have the "Use Part Based Corner Parameters and Trend Chart Setups" checkbox checked on each monitoring computer then the files you want to copy will be in the same directory on that computer



If not, then two of the files will be found in the "c:\v5\data" directory on the monitoring computer...



and the "display.ini" file will be in the "c:v5\exes: directory on the monitoring computer.

