




at 3Ghz getting too hot



at 2Ghz not meeting deadline



at 2Ghz with symetric perforation



at 2Ghz with asymmetric perforation

