

Name: Environmental topography

[<Files\\Borno>](#) - § 2 references coded [0.31% Coverage]

Reference 1 - 0.11% Coverage

4.The nature of the soil that cannot support

Reference 2 - 0.20% Coverage

5.Rocking terrain are so difficult for the construction of toilet to a high depth

[<Files\\Plateau>](#) - § 1 reference coded [0.12% Coverage]

Reference 1 - 0.12% Coverage

Environmental set up, especially hilly environment