

See github.com/pepaslabs/lm399-stick

For R_f , R_g and R_z , a 1% drift causes roughly 1ppm V_z error.
This is an attenuation of about 10,000:1.
Therefore, 100ppm/K 1% metal film are sufficient.

