

Room Inspection Report

Generated: 7 January 2026 at 9:58 AM

Room Summary

| | |
|----------------|---------------------|
| Floor Area | 0.00 m ² |
| Wall Area | 9.52 m ² |
| Ceiling Height | 2.34 m |
| Volume | 0.00 m ³ |

Detected Surfaces

| | |
|---------|---|
| Walls | 3 |
| Doors | 1 |
| Windows | 0 |

Wall Measurements

- Wall 1: 1.56 m × 2.34 m (3.65 m²)
- Wall 2: 1.47 m × 2.34 m (3.43 m²)
- Wall 3: 1.04 m × 2.34 m (2.44 m²)

Damage Assessment

| | |
|--------------------|------|
| Overall Condition | GOOD |
| Total Issues Found | 1 |
| Critical Issues | 0 |
| High Priority | 0 |

LOW PRIORITY



1. Hole - Wall

Size: 3.0 cm × 5.0 cm (14.9 cm²)

A small hole or indentation in the wall with chipped edges.

Recommendation: Patch with spackle or joint compound, sand smooth, and repaint.