

Room Inspection Report

Generated: 7 January 2026 at 10:41AM

Room Summary

Floor Area	0.00 m ²
Wall Area	10.07 m ²
Ceiling Height	2.34 m
Volume	0.00 m ³

Detected Surfaces

Walls	3
Doors	1
Windows	0

Wall Measurements

- Wall 1: 1.88 m × 2.34 m (4.40 m²)
- Wall 2: 1.38 m × 2.34 m (3.24 m²)
- Wall 3: 1.04 m × 2.34 m (2.44 m²)

Damage Assessment

Overall Condition	GOOD
Total Issues Found	1
Critical Issues	0
High Priority	0

LOW PRIORITY



1. Hole - Wall

Size: 3.1 cm × 4.1 cm (12.8 cm²)

Small indentation or hole in the drywall surface, likely caused by a minor impact.

Recommendation: Patch the area with a small amount of spackle or drywall joint compound, sand until flush with the wall once dry, and then repaint with matching paint.