

5.25.10/200 E 32/H. OFFICE

150

BUILDING INFORMATION

3 Number of stories

PLAN

- ☒ Square or rectangular
☐ Wing-and-gable
☐ Asymmetrical

FOUNDATION

- ☒ Pier and beam
☐ Stone
☐ Brick
☐ Slab

EXTERIOR WALLS

- ☒ Wood
☐ Stucco
☐ Stone
☐ Brick
☐ Synthetic siding
DROP + CENTER (type)
2 MATCH

ROOF TYPE

- ☒ Gable CLIPPED + COPULA
☐ Hipped
☐ Flat
☐ Gambrel
☐ Dormers
☐ Other (type)
☐ Other (type)



- ☐ Exposed rafter ends
☐ Brackets

ROOF MATERIALS

- ☒ Composition shingles
☐ Tile
☐ Metal
☐ Other (type)

CHIMNEYS

- ☐ Number
☐ Exterior ☒ Interior
☒ Brick
☐ Stone
☐ Other (type)

WINDOWS

- ☒ Wood sash
☐ Aluminum sash
☐ Vinyl
☐ Casement
☐ Decorative screens

FRONT PORCH

- ☐ None
☐ Full-width
☒ Partial-width 1 SOUTH 1 WEST
☐ Independent
☐ Inset
☐ Wraparound

PORCH ROOF

- ☒ Gabled (WEST) CLIPPED (SOUTH)
☐ Hipped
☒ Shed (SOUTH)

PORCH POSTS

- (SOUTH) (WEST)
☐ Full height
☒ On piers ON PIERS
STUCCO (pier material) WOOD
☒ Turned wood (WEST)
☒ Square wood
☐ Metal

PORCH RAILINGS

- ☒ None (WEST)
☐ Turned wood
☒ Square wood + STUCCO (SOUTH)
☐ Metal

DOOR FEATURES

- ☒ Glazing
☒ Transom
☐ Sidelights

LANDSCAPE FEATURES

- ☒ Fence WOOD (material) @ EAST P.L.
☐ (height)
☐ Wall (material)
☐ (height)
☐ Other

OUTBUILDINGS

- ☒ Detached single-story garage DEMOLISHED IN 2000?
☐ Garage apartment (2-story)
WOOD CENTER M. Wall material
MTL. Roof material
CORRUGATED Roof type

☐ Other



WEST ELEV