

Inspection Report		
Truckserialnumber:	7301234	
Truckmodel:	730	
Inspectionid:	56748	
Inspectorname:	John Lauda	
Inspectionemployeeid:	EMP001	
Inspectiondatetime:	2024-08-10T14:30:00Z	
Inspectionlocation:	Warehouse A	
Geocoordinates:	40.7128,-74.0060	
Servicemeterhours:	15000	
Inspectorsignature:	JohnDoeSignature	
Customername:	Acme Corp	
Customerid:	CUST12345	
Tires:		
Tirepressure:		
Leftfront:	32	
Rightfront:	30	
Leftrear:	32	
Rightrear:	30	

Tirecondition:	
Leftfront:	Good
Rightfront:	Ok
Leftrear:	Needs Replacement
Rightrear:	Good
Overalltiresummary:	All tires are in good condition except the left rear which needs replacement.
Attachedimages:	tire1.jpg, tire2.jpg, tire3.jpg, tire4.jpg
Battery:	
Batterymake:	CAT
Batteryreplacementdate:	2023-12-01T00:00:00Z
Batteryvoltage:	12V
Batterywaterlevel:	Good
Batterycondition:	N
Batteryleakorrust:	N
Batterysummary:	The battery is in good condition with no leaks or rust.
Attachedimages:	battery1.jpg
Exterior:	

Rustdentordamage:	Y
Oilleakinsuspension:	N
Exteriorsummary:	There is some minor rust and a small dent on the rear bumper.
Attachedimages:	exterior1.jpg, exterior2.jpg
Brakes:	
Brakefluidlevel:	Ok
Brakeconditionfront:	Good
Brakeconditionrear:	Ok
Emergencybrake:	Good
Brakesummary:	Brakes are in good condition overall.
Attachedimages:	brakes1.jpg
Engine:	
Rustdentordamage:	N
Engineoilcondition:	Good
Engineoilcolor:	Clean
Brakefluidcondition:	Good
Brakefluidcolor:	Clean

Oilleakinengine:

N

Enginesummary:

Engine is in good condition with no signs of rust or leaks.

Attachedimages:

engine1.jpg

Voiceofcustomer:

Customerfeedback:

The inspection was thorough and well documented.

Attachedimages:

feedback1.jpg