

**Performa for the Safety of School Building**  
**(To be filled by the head of School)**

1. Name of the School: **HVM Convent School**
2. Location: **Karamsar Colony, New Subhash Nagar,  
Basti Jodhewal, Ludhiana. Punjab**
3. Plot Area: **7911.60 Sq. Mtr. or 85128.81 Sq. Ft.**
4. Plinth Area: **22851.68 Sq. Ft.**
5. Number of Storey: **Three (First, Second and Third)**
6. Year of construction of building: **2010 – 11**
7. Supervision of the qualified engineer
  - (a) Name of Engineer **Mr. Jatinder Malhotra**
  - (b) Address **180-J, 2<sup>nd</sup> Floor, Sarabha Naar, Ludhiana.  
Punjab.**
  - (c) Set of structure drawing used in the construction, if available: **Yes, Attached**
  - (d) Name of the Architect: **Mr. Jatinder Malhotra  
(Malhotra & Associates)**
8. Whether the building has been constructed for the purpose of
  - (a) School **School**
  - (b) Residential purpose and converted for the use as a school **--**
9. Material used for roof
  - (a) RCC slabs **RCC Slabs**
  - (b) PS joints and battens **N.A.**
  - (c) Wooden joints & battens **N.A.**
10. Material used for walls:
  - (a) Mud mortar
  - (b) Cement Mortar **Cement Mortar**
  - (c) Plaster
    - (i) Lime mortar
    - (ii) Cement mortar **Cement Mortar**
11. Flooring:
  - (a) Conglomerate **Conglomerate**
  - (b) Terrazzo **N.A.**
  - (c) Brick Paving **N.A.**
12. Detailed drawing indicating of rooms along with size of doors and windows.  
**Structural Drawing Attached**

*Sunita Kumari*  
Principal  
HVM Convent Sr. Sec. School  
Signature with stamp of  
The head of school/institute

## Part II

(To be filled by S.D.E. of P.W.D.B & R Department)

No. D/2020-21/17

- a. I have visited the above mentioned school on 9/6/2020 Dt. 11.6.2020 and have visually inspected it from all angles of safety and I find it fit for normal use as a school building.
- b. In case any addition/alternation or expansion and modification to this building is to be carried out the same be carried out under the supervision of a technically qualified engineer & this certificate may again be obtained after the completion from the undersigned.
- c. In case the building is affected by flood or if there is settlement of walls/foundation or caving of roofs etc. immediately inspection of undersigned be arranged to check the stability and safety of the building.
- d. This building can be safe by occupied for normal use up to year 31-3-2021

Sub Divisional Engineer,  
Provincial Sub Division No. 3,  
P.W.D. B&R, Br. LUDHIANA.

**S.D.E.P.W.D. (B & R)**  
**Provincial Sub Division**  
**Ludhiana**