

Change Order Report For Project

VCU.PrjPcb And VCU.PrjPcb

Action	Object	Change Document	Status
Add Components			
Add	C1	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C2	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C3	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C4	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C5	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C6	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C7	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C8	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C9	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C10	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C11	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C12	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C13	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C14	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C15	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C16	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C17	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C18	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C19	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C20	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C21	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C22	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C23	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C24	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	C25	To PCB.PcbDoc	Footprint Not Found CAP 0603 16
Add	F1	To PCB.PcbDoc	Footprint Not Found FUSE 3587-1
Add	F2	To PCB.PcbDoc	Footprint Not Found FUSE 3587-1
Add	F3	To PCB.PcbDoc	Footprint Not Found FUSE 3587-1
Add	F4	To PCB.PcbDoc	Footprint Not Found FUSE 3587-1
Add	F5	To PCB.PcbDoc	Footprint Not Found FUSE 3587-1
Add	F6	To PCB.PcbDoc	Footprint Not Found FUSE 3587-1
Add	F7	To PCB.PcbDoc	Footprint Not Found FUSE 3587-1
Add	IC1	To PCB.PcbDoc	Footprint Not Found ST LQFP-100
Add	R1	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R7	To PCB.PcbDoc	Footprint Not Found RES 2512 64
Add	R8	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R30	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R33	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R34	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R36	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R38	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R39	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R42	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R43	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R46	To PCB.PcbDoc	Footprint Not Found RES 0805 20
Add	R47	To PCB.PcbDoc	Footprint Not Found RES 0805 20
Add	R48	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R49	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R50	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R52	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R53	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R54	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R55	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R56	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R57	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R58	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R59	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	R60	To PCB.PcbDoc	Footprint Not Found RES 0603 16
Add	S1	To PCB.PcbDoc	Footprint Not Found C&K KXT3
Add	Y1	To PCB.PcbDoc	Footprint Not Found ABRACON A