



ARM CoreSight™  
ATB Async Bridge (TM923)  
**Errata Notice**

This document contains all errata known at the date of issue in supported releases up to and including r0p0 of CoreSight ATB Async Bridge

**Proprietary notice**

Words and logos marked with ® or ™ are registered trademarks or trademarks of ARM Limited in the EU and other countries, except as otherwise stated below in this proprietary notice. Other brands and names mentioned herein may be the trademarks of their respective owners.

Neither the whole nor any part of the information contained in, or the product described in, this document may be adapted or reproduced in any material form except with the prior written permission of the copyright holder.

The product described in this document is subject to continuous developments and improvements. All particulars of the product and its use contained in this document are given by ARM Limited in good faith. However, all warranties implied or expressed, including but not limited to implied warranties of merchantability, or fitness for purpose, are excluded.

This document is intended only to assist the reader in the use of the product. ARM Limited shall not be liable for any loss or damage arising from the use of any information in this document, or any error or omission in such information, or any incorrect use of the product.

**Document confidentiality status**

This document is Non Confidential.

**Web address**

<http://www.arm.com/>

**Feedback on the product**

If you have any comments or suggestions about this product, contact your supplier giving:

- The product name
- A concise explanation of your comments.

**Feedback on this document**

If you have any comments on about this document, please send email to <mailto:errata@arm.com> giving:

- The document title
- The documents number
- The page number(s) to which your comments refer
- A concise explanation of your comments

General suggestion for additions and improvements are also welcome.

## Contents

INTRODUCTION	5
ERRATA - CATEGORY 1	7
There are no Errata in this Category	7
ERRATA - CATEGORY 2	8
There are no Errata in this Category	8
ERRATA - CATEGORY 3	9
There are no Errata in this Category	9
ERRATA - DOCUMENTATION	10
There are no Errata in this Category	10

## Introduction

### Scope

This document describes errata categorised by level of severity. Each description includes:

- the current status of the defect
- where the implementation deviates from the specification and the conditions under which erroneous behavior occurs
- the implications of the erratum with respect to typical applications
- the application and limitations of a 'work-around' where possible

### Categorisation of Errata

Errata recorded in this document are split into three levels of severity:

Category 1      Behavior that is impossible to work around and that severely restricts the use of the product in all, or the majority of applications, rendering the device unusable.

Category 2      Behavior that contravenes the specified behavior and that might limit or severely impair the intended use of specified features, but does not render the product unusable in all or the majority of applications.

Category 3      Behavior that was not the originally intended behavior but should not cause any problems in applications.

## **Change Control**

### **04 Jun 2007: Changes in Document v1**

This is the initial release of this document

## **Errata - Category 1**

**There are no Errata in this Category**

## Errata - Category 2

**There are no Errata in this Category**



## **Errata - Category 3**

**There are no Errata in this Category**

## Errata - Documentation

**There are no Errata in this Category**