



# Vehicle Inspection Report

Prepared by CertifyCars LLC

<b>Vehicle Make</b>	-
<b>Model</b>	-
<b>Year</b>	-
<b>VIN</b>	-
<b>Registration No.</b>	-
<b>Inspection Date</b>	28-08-2025
<b>Inspector</b>	N/A

**Disclaimer:** This inspection report reflects the condition of the vehicle at the time of inspection. It does not guarantee future performance. CertifyCars LLC is not liable for any hidden defects not visible during inspection.

**Body Details**

Inspection Point	Result
Id	3
Request id	2
Front bumper	1
Rear bumper	0
Bonnet	1
Boot lid	0
Left front wing	1
Right front wing	0
Left front door fit	0
Right front wing fit	1
Right front door fit	1
Left rear door fit	0
Right rear door fit	1
Left rear quarter panel fit	0
Right rear quarter panel fit	1
Roof panel alignment	0
Fender mounting condition	1
Panel gap uniformity	0
External trim condition	1
Molding clips present	0

Inspection Point	Result
Door seals fitment	1
Boot seal fitment	0
Fuel filler door operation	1
Body fasteners intact	0
Tow eye point secure	1
Bumper reinforcement visible	0
Undercarriage guards	1
Panel repair signs	0
Exterior accessory fitment	1
Created at	2025-08-28T10:56:47.000000Z
Updated at	2025-09-04T09:57:32.000000Z

## Glass &amp; Mirrors

Inspection Point	Result
Id	3
Request id	2
Windshield condition	No damage / Excellent condition, Minor scratches, Chips present, Cracks present, Hazy / Reduced visibility, Loose / Improper fitment, Repaired (chip/crack repair visible), Replacement recommended

Inspection Point	Result
Windshield wiper function	Working properly,Slow / irregular movement,Not working,Noise during operation
Wiper blade wear	Good condition
Rear wiper function	Working properly
Side window operation lf	Smooth operation
Side window operation rf	Smooth operation
Side window operation lr	Smooth operation
Side window operation rr	Smooth operation
Rear window condition	No damage / Excellent condition
Sunroof operation	Smooth operation
Sunroof drainage check	No leakage / Proper drainage
Sunroof glass condition	Excellent / No damage
Left external mirror function	Fully functional
Right external mirror function	Fully functional
Mirror adjustment motors	Working properly,Slow movement,Noisy operation,Not working
Comments	
Created at	2025-08-28T10:56:47.000000Z
Updated at	2025-09-04T09:57:32.000000Z