



TO DO
-Main ROM socket pins are too wide (too far between cols)
-Add debug pin headers for SPI pins
-Add an additional VCC/GND header or two (scope, LCD power, etc.)