



 VALUE INTEGRATOR	MAINTENANCE WORK INSTRUCTIONS	SOP No: TSOP101
	DIE INSPECTION	Rev: 0.0
		Date: 16 OCT 2025

No.	INSTRUCTIONS	VISUALS	KEY POINTS / CONTACTS
1.	<ul style="list-style-type: none"> Place die on rubbers evenly on the die area. Refer to MAW 68 for die loading setting and turning. 		
2.	Put up sign. (DIE CHECK IN PROGRESS)		

Controlled By:	Maintenance	Approved By:	Zondi, Ndumiso	Page 1 of 1
Date: Thursday, October 16, 2025				

UNCONTROLLED WHEN PRINTED WITHOUT RED CONTROLLED STAMP & SIGNATURES