



| | | |
|-------------------------------------------------------------------------------------------------------|-------------------------------|-------------------|
|  VALUE INTEGRATOR | MAINTENANCE WORK INSTRUCTIONS | SOP No: TSOP102 |
| | MAINTENANCE WORK INSTRUCTIONS | Rev: 0.0 |
| | | Date: 20 OCT 2025 |

| No. | INSTRUCTIONS | VISUALS | KEY POINTS / CONTACTS |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|----------------------------------------------------------|
| 1. | CASTING: Visually inspect for any cracks. | | □ |
| 2. | BLADE: Visually check for any chips <ul style="list-style-type: none"> • Tighten Bolts • Use an impact • Wrench (set @ No. 2) | | □ |
| 3. | Loosen housing Check for proper performance (push in, must return) |  | If found faulty, replace with lock tight. |

| | | | | |
|--------------------------------|-------------|--------------|----------------|-------------|
| Controlled By: | Maintenance | Approved By: | Zondi, Ndumiso | Page 1 of 1 |
| Date: Monday, October 20, 2025 | | | | |

UNCONTROLLED WHEN PRINTED WITHOUT RED CONTROLLED STAMP & SIGNATURES