




| | | |
|---|-------------------------------|-------------------|
|  VALUE INTEGRATOR | MAINTENANCE WORK INSTRUCTIONS | SOP No: TSOP7 |
| | DIE INSPECTION | Rev: 00 |
| | | Date: 11 OCT 2025 |

| No. | INSTRUCTIONS | VISUALS | KEY POINTS / CONTACTS |
|-----|---|---|--|
| 1. | <p>Place die on rubbers evenly on the die area.</p> <p>Refer to MAW 68 for die loading setting and turning.</p> |  | <p>ENSURE PERSONNAL PROTECTIVE EQUIPMENT (PPE) IS WORN: -</p> <ol style="list-style-type: none"> 1. Hard hat with chin strap 2. Steel cap boots 3. Gloves. 4. Torch. 5. Beware of sharp edges.  |

| | | | | |
|----------------------------------|-------------|--------------|----------------|-------------|
| Controlled By: | Maintenance | Approved By: | Zondi, Ndumiso | Page 1 of 1 |
| Date: Saturday, October 11, 2025 | | | | |

UNCONTROLLED WHEN PRINTED WITHOUT RED CONTROLLED STAMP & SIGNATURES