



PROPOSAL REPORT

Alaska Property Management - North Slope Office

Mary Manager

Snowfox Estates

RFP#: 1000204

Concrete Restoration

ABOUT THIS REPORT

This comprehensive report includes all of the participating vendors and their responses, based on the identical scope of work provided to each company. The first page of the report includes an easy-to-read comparison of the more essential items related to each vendor, including contact information, compliance status, and proposal pricing. The second page includes a breakdown of each vendor's price, line-item by line-item. Following the second page are complete responses to the scope of work provided, including the vendor's recommended solution, warranties, and attached documents (if applicable)..

PROTECTING THE COMMUNITY

Each and every vendor who submitted a quote for this request has met, or exceeded, the predetermined minimum requirements for insurance and licensing (if applicable). Supporting documents (insurance policies, licenses, etc.) are provided in the digital version of the entire proposal report. In addition, every vendor within this report has an "apple rating" that is based on the quality of their work and customer service with other communities. This should help increase the likelihood of hiring the best contractor at the best possible price.

UNDERSTANDING A VENDOR'S PRICE

Vendor pricing can vary greatly, even when compared "apples-to-apples". Some of the many reasons for varying quotes include acquisition fees, insurances, employee benefits, sales commissions, warranties, capital equipment, quality of workforce and materials, experience of estimators, and profit margin. Multiple bids through a competitive bidding process is an important part of the solution to finding the right vendor for the job.

STAYING ORGANIZED

Any information related to this report has been digitally recorded for future reference or use. All related materials will be available for review in case a re-bid, punch-out list, warranty request, or dispute regarding the final product or service with a hired vendor is required.







THIS IS NOT A SEALED BID. ALL PRICES WERE VISIBLE UPON BID SUBMISSION FROM VENDORS.

Concrete Restoration Snowfox Estates | RFP #1000204

Industry Solicited: **Structural Concrete, Steel, Shear, Curtainwall**
Service Location:

Closed On: **11-02-2014**
Proposals Submitted: **5**
Alt.Proposals Submitted: **1**

High Bid: **\$95,850.00**
Low Bid : **\$44,567.00**
Average Bid : **\$80,506.60**



DESCRIPTION	VENDOR 1	VENDOR 2	VENDOR 3
			
Company Name:	Alaska Premier Contractors	Alaska Reindeer Construction	AA Alaska Contractors
Vendor Apple Rating: (Based on customer surveys & vendor follow through)	 4 Out of 5	 4 Out of 5	 4 Out of 5
Vendor Address:	879546 Denali Hwy, North Slope, Alaska 77777	5687 Tundra Drive, North Slope, Alaska 77777	789456 Transcan Hwy, North Slope, Alaska 77777
Contact Name:	Betsy	Stu	Rudolph
Office Number:	(555) 521-7777	(555) 546-5555	(555) 564-1212
Alt.Number:	N/A	N/A	N/A
Mobile Number:	N/A	N/A	N/A
Email Address:	demo5@myvendorcenter.com	demo6@myvendorcenter.com	demo4@myvendorcenter.com
Business Established:	1999	1946	1984
General Liability:	\$3,000,000	\$4,000,000	\$5,000,000
Workers Comp. Policy?	Yes	Yes	Yes
Meets Compliance Standards?	Yes	Yes	No
In-House Vendor? (Vendor affiliated with management company)	No	No	No
TOTAL AMOUNT PROPOSED:	\$87,250.00	\$44,567.00	\$95,850.00
Alternate Proposal?	\$89,500.00	No	No

Concrete Restoration Snowfox Estates | RFP #1000204




Industry Solicited: **Structural Concrete, Steel, Shear, Curtainwall**
Service Location:

Closed On: **11-02-2014**
Proposals Submitted: **5**
Alt.Proposals Submitted: **1**


High Bid: **\$95,850.00**
Low Bid : **\$44,567.00**
Average Bid : **\$80,506.60**

DESCRIPTION	VENDOR 4
	
Company Name:	Alaska North Slope Restoration Contracting
Vendor Apple Rating: (Based on customer surveys & vendor follow through)	 4 Out of 5
Vendor Address:	45687 Prudoe Hwy, North Slope, Alaska 444444
Contact Name:	Corey Smith
Office Number:	(7075551212) -
Alt.Number:	N/A
Mobile Number:	N/A
Email Address:	demo14@myvendorcenter.com
Business Established:	1942
General Liability:	\$0
Workers Comp. Policy?	No
Meets Compliance Standards?	No
In-House Vendor? (Vendor affiliated with management company)	No
TOTAL AMOUNT PROPOSED:	\$85,366.00
Alternate Proposal?	No

ITEMIZED PRICING BREAKDOWN

DESCRIPTION	VENDOR1	VENDOR2	VENDOR3
			
Company Name:	Alaska Premier Contractors	Alaska Reindeer Construction	AA Alaska Contractors
Line Item #1 Pricing: Concrete Restoration	\$87,000.00	\$44,567.00	\$95,500.00
Line Item #2 Pricing: Waste removal and site protection	\$250.00	\$0.00	\$350.00
TOTAL AMOUNT PROPOSED:	\$87,250.00	\$44,567.00	\$95,850.00

ITEMIZED PRICING BREAKDOWN

DESCRIPTION	VENDOR4
	
Company Name:	Alaska North Slope Restoration Contracting
Line Item #1 Pricing: Concrete Restoration	\$45,678.00
Line Item #2 Pricing: Waste removal and site protection	\$39,688.00
TOTAL AMOUNT PROPOSED:	\$85,366.00

LINE ITEM #1: Concrete Restoration

500 Linear feet of balcony on clubhouse to be restored per engineering.

See attached engineer's instructions.

File(s) Provided to Vendors: ConcRest.pdf

Alaska Premier Contractors:	LINE ITEM PRICE: \$ 87,000.00
NOTES: Work performed to attached specifications. Pricing includes up to 500 linear ft. of #5 rebar and 500 cu. ft. of epoxy concrete. If additional material is required due to additional hidden dama	
EXCEPTION(S): NONE	
Alaska Reindeer Construction:	LINE ITEM PRICE: \$ 44,567.00
NOTES: Will restore balcony to original construction per engineer's specifications.	
EXCEPTION(S): NONE	
AA Alaska Contractors:	LINE ITEM PRICE: \$ 95,500.00
NOTES: 1. AT AREAS WITH SIGNS OF CORROSION OR WITH EXPOSED BARS THE CONCRETE SHALL BE CHIPPED PROVIDING A VERTICAL SURFACE AT LEAST 1" BEYOND EXISTING BAR. CONCRETE SHALL BE REMOVED ALL THE WAY ALONG REINFORCING BARS UNTIL THERE IS NO SIGNS OF CORROSION. 2. CLEAN CUT AREA THOROUGHLY AND COAT EXPOSED REINFORCEMENT WITH A WATER BASED CORROSION INHIBITOR. 3. IF UPON CLEANING EXISTING REINFORCEMENT IT LOOSES 10% OR MORE OF ITS AREA, IT SHALL BE REPLACE BY ANOTHER BAR. 4. AFTER THE CLEANING AND CORROSION INHIBITOR APPLICATION IS FINISHED, THE TIP OF THE BALCONY SHALL BE FORMED AND RE-POURED WITH EPOXY GROUT OF AT LEAST 5,000 PSI COMPRESSIVE STRENGTH. 5. WHERE BAR REPLACEMENT IS REQUIRED PROVIDE 24" LAP SPLICE AT ENDS OF NEW REPLACEMENT BARS. ALSO PROVIDE #3 HAIRPINS PLACED AS SHOWN AND CONNECTED TO EXISTING CONCRETE WITH EPOXY EPCON C6 WITH 3" EMBEDMENT INTO EXISTING CONCRETE.	
EXCEPTION(S): NONE	
Alaska North Slope Restoration Contracting:	LINE ITEM PRICE: \$ 45,678.00
NOTES: 500 l.f. of concrete at balconies will be renovated to like-new conditions. Any more damage found during repairs will be considered a change order.	
EXCEPTION(S): NONE	

LINE ITEM #2: Waste removal and site protection

- 1) Site will be in use - use appropriate safety precautions.
- 2) All dust and debris must be contained.
- 3) All association and visitor property must be protected during all operations.

File(s) Provided to Vendors:

Alaska Premier Contractors:	LINE ITEM PRICE: \$ 250.00
NOTES: We will comply with these requirements.	
EXCEPTION(S): NONE	
Alaska Reindeer Construction:	LINE ITEM PRICE: \$ 0.00
NOTES: Included in price	
EXCEPTION(S): NONE	
AA Alaska Contractors:	LINE ITEM PRICE: \$ 350.00
NOTES: WE WILL COMPLY WITH THESE REQUIREMENTS	
EXCEPTION(S): NONE	
Alaska North Slope Restoration Contracting:	LINE ITEM PRICE: \$ 39,688.00
NOTES: This will require several barricades, tarp, and visqueen. We will protect all owner-related items and property from overspray, concrete dust, and other related product. If our protected site is disturbed by owners, then we will not take responsibility for any preceding damage.	
EXCEPTION(S): NONE	

GENERAL NOTES & WARRANTY:

Alaska Premier Contractors:

GENERAL NOTES:

Pricing based on engineer evaluation. Any additional damage discovered will be quoted as a separate item or change order.
10% to start. 30% at commencement, balance on completion.ATTACHMENT(S):

WARRANTY:

1 year warranty, materials and labor.

ATTACHMENT(S): No Files

Alaska Reindeer Construction:

GENERAL NOTES:

Will take approx. 4 weeks to complete as long as there are no disturbances with weather.
ATTACHMENT(S):

WARRANTY:

1 year parts and service

ATTACHMENT(S): No Files

AA Alaska Contractors:

GENERAL NOTES:

Terms: 10% start - 40% Demolition complete - 50% Work CompleteATTACHMENT(S):

WARRANTY:

1 Year materials and labor

ATTACHMENT(S): No Files

Alaska North Slope Restoration Contracting:

GENERAL NOTES:

NoneATTACHMENT(S):

WARRANTY:

1 year on parts. 2 years on labor.

ATTACHMENT(S): No Files

COMPLIANCE DOCUMENTS

General Liability

Occur

Each Occurrence: \$ 1,000,000.00

General Aggregate: \$ 0.00 | Applies To: Proj

Alaska Premier Contractors:

Occupational License: [Business_License.pdf](#)

Professional License: [biz.pdf](#)

General Liability Insurance: [Demo_COI.pdf](#)

Workers Comp Insurance: [Demo_COI.pdf](#)

W-9: [fw9.pdf](#)

Alaska Reindeer Construction:

Occupational License: [Business_License.pdf](#)

Professional License: [biz.pdf](#)

General Liability Insurance: [Demo_COI.pdf](#)

Workers Comp Insurance: [Demo_COI.pdf](#)

W-9: [fw9.pdf](#)

AA Alaska Contractors:

Occupational License: [Business_License.pdf](#)

Professional License: [biz.pdf](#)

General Liability Insurance: [Demo_COI.pdf](#)

Workers Comp Insurance: [Demo_COI.pdf](#)

W-9: [fw9.pdf](#)


Alaska North Slope Restoration Contracting:

Concrete Restoration Snowfox Estates | RFP #1000204


Industry Solicited: **Structural Concrete, Steel, Shear, Curtainwall**
Service Location:

Closed On: **11-02-2014**
Proposals Submitted: **5**
Alt.Proposals Submitted: **1**

High Bid: **\$95,850.00**
Low Bid : **\$44,567.00**
Average Bid : **\$80,506.60**

DESCRIPTION	VENDOR 1
	
Company Name:	Alaska Premier Contractors
Vendor Apple Rating: (Based on customer surveys & vendor follow through)	 4 Out of 5
Vendor Address:	879546 Denali Hwy, North Slope, Alaska 77777
Contact Name:	Betsy
Office Number:	(555) 521-7777
Alt.Number:	N/A
Mobile Number:	N/A
Email Address:	demo5@myvendorcenter.com
Business Established:	1999
General Liability:	\$3,000,000
Workers Comp. Policy?	Yes
Meets Compliance Standards?	Yes
In-House Vendor? (Vendor affiliated with management company)	No
TOTAL AMOUNT PROPOSED:	\$89,500.00
Alternate Proposal?	\$89,500.00

ITEMIZED PRICING BREAKDOWN

DESCRIPTION	VENDOR1
	
Company Name:	Alaska Premier Contractors
Line Item #1 Pricing: Concrete Restoration	\$87,000.00
Line Item #2 Pricing: Waste removal and site protection	\$2,500.00
TOTAL AMOUNT PROPOSED:	\$89,500.00

LINE ITEM #1: Concrete Restoration

500 Linear feet of balcony on clubhouse to be restored per engineering.

See attached engineer's instructions.

File(s) Provided to Vendors: ConcRest.pdf

Alaska Premier Contractors:	LINE ITEM PRICE: \$ 87,000.00
<p>NOTES: Work performed to attached specifications. Pricing includes up to 500 linear ft. of #5 rebar and 500 cu. ft. of epoxy concrete.</p> <p>If additional material is required due to additional hidden damage</p> <p>See extended warranty offer.</p> <p>EXCEPTION(S): NONE</p>	

LINE ITEM #2: Waste removal and site protection

- 1) Site will be in use - use appropriate safety precautions.
- 2) All dust and debris must be contained.
- 3) All association and visitor property must be protected during all operations.

File(s) Provided to Vendors:**Alaska Premier Contractors:****LINE ITEM PRICE: \$ 2,500.00****NOTES:** We will comply with these requirements.**EXCEPTION(S): NONE**

GENERAL NOTES & WARRANTY:

Alaska Premier Contractors:

GENERAL NOTES:

Pricing based on engineer evaluation. Any additional damage discovered will be quoted as a separate item or change order.
10% to start. 30% at commencement, balance on completion.

WARRANTY:

Extended warranty option: 5 Years

ATTACHMENT(S): No Files