

# Incident Report - Summary

Internal notes

Time	Event
07:15	Leak discovered under sink; main shut off
08:30	DryPro on site; moisture readings taken
09:15	Mitigation begun; affected cabinetry documented

No police/fire involvement; non-criminal water loss.