



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 16/05/2025

Area: WT

Equipment	Job
OT 4	control cable tied properly and Revers limit cam found damaged shifted to spare all wires connected
OT 1 series	panel and motor side ppm done
CC2 and 3	area lighting ,circuit problem rectified and 1 no choke (400W) replaced
CT house	lighting nutral cable found melted,replaced connectors and connected wire
OP 8	panel and motor side blowing and ppm done
OP 5	D4,rotor slip rings buffing done and fixed brushes with holders motor kept in circuit
OP 5	track lifted by Railways @ col no 3 to 6 both sides, tested found OK (no rolling)
CP 1,2,4 OP 2,3 and 4	after rake maintenance done
MIS	OP 8 /D2 removed drive checked found one phase IGBT and diode failed