



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/12/2025

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment       | Problem   | Action  | From     | To       | Remarks |
|-------|------|-----------------|---|---|----------|----------|---------|
| 1     | OHP  | CC 40 SCr 2     | signal missing,                                     | LT done than ok   | 17:00:00 | 17:30:00 |         |
| 2     | OHP  | CO 48           | olr acted   | reset   | 20:50:00 | 21:00:00 |         |
| 3     | OHP  | TBS on CO 5A    | LT not taking place,M\$ tripped continuously on olr | M4 connection removed   | 15:30:00 | 15:45:00 |         |
| 4     | OHP  | BRC on CO 28    | Reported B/C not running                            | Control checked and found okay. Tested okay   | 21:00:00 | 21:20:00 |         |
| 5     | CHP  | CC-203 on CC-29 | Reported flap gate not changing through system      | Checked and found PLC fault at CCR.Remote I/O at LC-5 no power found due to I/C-2 tripped. I/C-2 made on and CCR PLC communication restored and tested okay | 19:24:00 | 20:30:00 |         |
| 6     | CHP  | CC 125          | olr acted   | reset   | 19:00:00 | 19:10:00 |         |
| 7     | CHP  | CC 38 SCR6      | Lt not working,OT acted                             | OT released   | 20:45:00 | 21:00:00 |         |
| 8     | CHP  | CC 32 R1        | b/c not running,olr acted                           | reset   | 16:00:00 | 16:15:00 |         |
| 9     | CHP  | CC 51           | mpd tripped   | reset   | 17:20:00 | 20:30:00 | 5 times |
| 10    | CHP  | CC 51           | motor tripped in olr                                | reset   | 18:36:00 | 18:40:00 |         |
| 11    | CHP  | CC 54           | olr acted 2 times                                   | reset   | 15:00:00 | 17:05:00 |         |
| 12    | CHP  | CC 114          | olr acted   | reset   | 21:20:00 | 21:30:00 |         |