



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 27/06/2025

Shift: B

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	tbs on co 24	rbc zss acting/return idler got missed	bypassed at module for operation requirement entered in log book	16:30:00	16:50:00	
2	OHP	co 26	tripped on olr	reset done 2times	17:33:00	17:37:00	
3	OHP	brc on co 30	cjd bypassed in A SHIFT	Cjd kept in ckt	14:25:00	14:50:00	
4	OHP	tbs on co 22	chute vibrator not working/olr acted	checked one phase got earthed /insulation done then ok	16:25:00	17:00:00	
5	OHP	co 37a	brs acted/	brs bypassed at module for operation requirement	17:18:00	17:25:00	
6	OHP	wobr on co 6a	luffing not taking place/solnoid valve stuckup	manually released then ok	16:36:00	17:00:00	
7	CHP	CC31	Tripped on over load	Reset done	14:25:00 15:20:00	14:30:00 15:25:00	
8	CHP	CC203	Flap gate position 29 side not healthy	Bypassed in panel side	14:50:00	15:00:00	
9	CHP	CC31	Tripped on over current	Reset done	15:15:00	15:20:00	
10	CHP	SCR5 on CC32	LT not working found MPCB 2 and 6 tripped	Reset done	16:05:00	16:15:00	
11	CHP	SCR9 on CC104	SCR9 yard inter lock found healthy	No problem	16:20:00	16:30:00	
12	CHP	SCR1 on CC35	Slewing not working foundMPCB2 tripped	Reset done	16:45:00	16:55:00	
13	CHP	SCR7 on CC39	BW not running found all healthy	Fault reset done then ok	18:05:00	18:15:00	



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 27/06/2025

Incharge(s): G Eswara Rao

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	SCR5 on CC32	LT not running found MPCB2 tripped	Reset done	19:00:00	19:10:00	
15	CHP	SCR5 on CC32	BC not running found over current acted due to over load on boom conveyor	Fault reset done then ok	20:05:00	20:20:00	
16	CHP	CC53	Pull card switches damaged cable removed and rejoined	Pull cord switches taken in to ckt	14:30:00	15:00:00	
17	CHP	CC117	Motor tripped on over load	Reset done	16:10:00	16:25:00	
18	CHP	CC131	Motor tripped on over load	Reset done	17:00:00	17:05:00	
19	CHP	CC28	TT flap gate tripped	Reset done	17:20:00	17:30:00	
20	CHP	CC114	BRs bypassed as per operational requirement	Bypassed	19:25:00	19:35:00	
21	WT	CC29	Flap gate tripped	reset done	14:20:00	14:30:00	
22	WT	OP9	After rake completion pusher pushed into tippler it went to no power zone ( power cut off section)	By providing jumpers pusher brought back to power zone and sent to parking area	21:05:00	21:45:00	