



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/05/2025

Shift: A

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO 32	CT not working	CT in local mode, kept in remote	09:00:00	09:15:00	
2	OHP	TIS on CO 25	Failed to start	K -35 relay not picking up properly. Manually picked up , then got free . Checked in remote mode, running ok	09:10:00	09:35:00	
3	OHP	TBS on CO 20	Left luff not working	OLR acted. reset done	09:45:00	10:00:00	
4	OHP	CO 35	OLR acted	reset done	08:30:00 12:05:00	08:35:00 12:10:00	
5	OHP	VF 10A Chute vibrator	Not working due to R phase got cut in motor TB	Re connected , then ok	12:30:00	12:40:00	
6	OHP	OM 13	Breaker tripping on load	Breaker changed with Gen shift	12:30:00	14:00:00	
7	OHP	CO 20 , CO 21	BRS bypassed in system	Bypassed bcz of OM 13 PRBLM.	13:30:00	13:45:00	To be normalized
8	CHP	CC 44	OLR acted	reset done	07:00:00	07:15:00	
9	CHP	CC 104 , SCR 9	BW not running	Emergency acted near BW . after released then ok	08:00:00	08:30:00	
10	CHP	CC 34 , SCR 2	LT not working	PCRD overtension acted, released	11:20:00	11:30:00	
11	CHP	CC 32 , SCR 5	BC not running	Overload tripped , reset done	13:30:00	13:45:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/05/2025

Shift: A

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	CC 34, SCR 2	BC stopping frequently. LT not working	. Also LT done due to signal missing . LT drive reset	12:45:00	13:30:00	