



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/06/2025

Shift: A

Incharge(s): V Balaji Naik

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------------------------|--|--|----------------------------------|----------------------------------|---------|
| 1 | OHP | CO11 | Over load trip | Reset done | 10:10:00 | 10:15:00 | |
| 2 | OHP | Co11 | MPCB tripped due to over load trip | Reset done | 07:15:00 | 07:25:00 | |
| 3 | OHP | TT1A flap gate | OLR acted reset done | Then ok | 08:00:00 | 08:45:00 | |
| 4 | OHP | BRC on Co26 | Slewing not working found drive over load acated | Reset done | 07:30:00 | 07:45:00 | |
| 5 | OHP | CO9 | Tripped in over load | Reset done | 12:30:00 | 12:45:00 | |
| 6 | CHP | CC131 | Over load trip 3 times due to over load | Informed operation and reset done | 07:30:00 08:00:00 08:15:00 | 07:35:00 08:05:00 08:20:00 | |
| 7 | CHP | CC54 | Over load acted | Reset done | 06:15:00 | 06:20:00 | |
| 8 | CHP | CC113 TIS | Bypassed as per operation request | Done | 13:00:00 | 13:10:00 | |
| 9 | CHP | CC29 | TT flap tripped | Reset done | 09:20:00 | 09:30:00 | |
| 10 | CHP | SCR5 on CC32 | LT not working found MPCB 4 tripped | Reset done | 06:25:00 | 06:35:00 | |
| 11 | CHP | All machines signal problem CCR | PLC micrologix replaced and IP sddress of PLC micrologix changed | Few mac addresses removed setting in Esteem modem changed to access from all to fixed given mac adresses | 08:30:00 13:15:00 | 12:30:00 13:30:00 | |
| 12 | CHP | R1 on CC31 | GVM side position not showing in CCR | Bypassed in programm and gate way also changed | 10:30:00 | 10:45:00 | |
| 13 | WT | OC1a | Over load acted | Reset done | 09:05:00 | 09:10:00 | |



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/06/2025

Incharge(s): V Balaji Naik

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|---|----------------------------------|----------|----------|---------|
| 14 | WT | OP1 | Not moving in reverse found jamming informed to operation | Breaker tripped in LC 2a made on | 11:30:00 | 11:35:00 | |
| 15 | WT | CO4 Carriage | Carriage drive tripped | Reset done | 11:00:00 | 11:10:00 | |