



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 16/05/2025

Incharge(s): Arnab Roy

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|---|--|----------------------|----------------------|-----------------------|
| 1 | OHP | CO 35 | OLR acted | reset done | 06:45:00 08:15:00 | 06:55:00 08:25:00 | |
| 2 | OHP | WOBR on CO 26 | No drive running | Down limit acted, reset done | 07:00:00 | 07:20:00 | |
| 3 | OHP | CO 16 | BRS to be bypassed | Bypassed as per operation request, in module | 10:15:00 | 10:20:00 | |
| 4 | OHP | TBS on CO 23 | LT not taking place | PCRD overtension acted, released | 12:40:00 | 12:55:00 | |
| 5 | CHP | CC 33, SCR 4 | LT not working (from C shift) | Operator cabin mains ON , fault reset done. Then LT working | 06:00:00 | 06:15:00 | |
| 6 | CHP | CC 32 | BRS to be bypassed | Bypassed a. Bypassed as per operation request . | 07:00:00 | 08:30:00 | Again kept in circuit |
| 7 | CHP | CC 112 , SCR 8 | Slewing not working | Slew brake pressure sensor switch problem. Switch interchanged from standby panel by instrumentation | 08:45:00 | 11:45:00 | |
| 8 | CHP | CC 125 | Overload acted | reset done | 13:20:00 | 13:25:00 | |
| 9 | CHP | CC 54 | Overload acted | reset done | 09:35:00 11:00:00 | 09:40:00 11:05:00 | |
| 10 | CHP | CC 104 , SCR 9 | Slew not working | Overload tripped , reset done | 13:20:00 | 13:40:00 | |
| 11 | WT | OP 9 | Not moving due to Reverse end limit acted | Limit released , then ok | 11:55:00 | 12:05:00 | |