



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/10/2025

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment     | Problem  | Action                                     | From     | To       | Remarks                  |
|-------|------|---------------|--|--|----------|----------|--------------------------|
| 1     | OHP  | WOBR on CO 25 | no power,pcrd cable divided in two piece from pendulum switch    | isolator checked,all fuse ok,megger done   | 00:40:00 | 01:40:00 | DNW will come in A shift |
| 2     | OHP  | CR 1          | tripped in Over current  | reset                                      | 05:15:00 | 05:25:00 |                          |
| 3     | OHP  | CO 77         | OLr acted  | reset                                      | 23:00:00 | 23:10:00 |                          |
| 4     | OHP  | CO 30 BRC     | LT not working,OT acted  | OT released                                | 00:02:00 | 00:15:00 |                          |
| 5     | OHP  | TBS on CO 21  | LT not working,control is in off from control desk               | made it on                                 | 05:00:00 | 05:15:00 |                          |
| 6     | OHP  | TBS on CO 21  | luffing not working,full jamming                                 | informed operation                         | 05:35:00 | 05:45:00 |                          |
| 7     | CHP  | CC 201,203    | OLR acted  | reset                                      | 22:50:00 | 22:59:00 |                          |
| 8     | CHP  | CC 31 SCr 4   | light not glowing,light having fault                             | rectified                                  | 23:50:00 | 00:05:00 |                          |
| 9     | CHP  | CC 31 SCR4    | BW not running,BW stucked ,after giving cmd b/w immediately stop | electrical side all ok,informed operation  | 00:05:00 | 00:35:00 |                          |
| 10    | CHP  | CC 37 SCR7    | LT not taking place,OT acted                                     | OT released                                | 01:00:00 | 01:10:00 |                          |
| 11    | CHP  | CC 40 SCr3    | luffing down limit bypass  | again kept in ckt                          | 02:40:00 | 02:50:00 |                          |
| 12    | CHP  | CC 40 SCR3    | LT not taking place,MPCB tripped,track jammed                    | made it on,informed operation for cleaning | 02:55:00 | 03:05:00 |                          |
| 13    | CHP  | CC 203 ,      | FG 29 signal missing   | panel side given high in new LC C1         | 04:00:00 | 04:15:00 |                          |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/10/2025

Incharge(s): Saurabh Kumar Yadav

Shift: C

| Sl No | Area | Equipment   | Problem                                  | Action  | From     | To       | Remarks           |
|-------|------|-------------|--|---|----------|----------|-------------------|
| 14    | CHP  | CC 38 SCR6  | LT MPCB 6 tripped                        | made it on  | 04:08:00 | 04:25:00 |                   |
| 15    | CHP  | CC 36 SCR 1 | BW olr acted                             | reset   | 04:50:00 | 05:00:00 |                   |
| 16    | CHP  | CC 28       | motor tripped in OLR,current value 700 A | informed operation ,they are not agreed and tell to give in local | 03:20:00 | 03:50:00 | 5 times olr acted |
| 17    | CHP  | CC 131      | olr acted                                | reset   | 04:00:00 | 04:05:00 | 2 times           |
| 18    | WT   | CP1         | no movement,emergency acted in pusher    | informed operation,emergency released                             | 23:30:00 | 23:45:00 | operation delay   |