



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/07/2025

Incharge(s): Amit Roy, K SANKARA RAO

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|--|---|----------|----------|--|
| 1 | OHP | CO 25 | OLR ACTED | RESET | 14:30:00 | 14:35:00 | |
| 2 | OHP | CO 29 | OLR ACTED | RESET | 16:50:00 | 17:00:00 | |
| 3 | OHP | CO 63(B)DRIVE | OLR ACTED | RESET | 19:30:00 | 19:45:00 | DUE TO BELT OFF CENTERING AND SMOKE COME FROM GEAR BOX |
| 4 | OHP | CO 66 | OLR ACTED | RESET | 19:30:00 | 19:40:00 | |
| 5 | OHP | CO 35 | OLR ACTED | RESET | 20:40:00 | 20:50:00 | |
| 6 | OHP | CO-33M BRC-4 | Reported LT not taking place | Checked and found Drive tripped. Reset done and tested okay | 21:20:00 | 21:30:00 | |
| 7 | CHP | CC 201 | OLR ACTED | RESET | 14:30:00 | 14:40:00 | |
| 8 | CHP | CC 203 | OLR ACTED | RESET | 14:30:00 | 14:40:00 | |
| 9 | CHP | CC202 | PC AND OLR ACTED | OLR RESET AND PC RELEASED | 14:30:00 | 14:45:00 | |
| 10 | CHP | CC 34 -SCR 2 | SLEW NOT TAKING PLACE DRIVE TRIP | RESET THAN OK | 15:20:00 | 15:35:00 | |
| 11 | CHP | CC 31 S-3 | SLEW NOT TAKING PLACE MATERIAL JAMMING | INFORMED TO OPERATION | 15:30:00 | 15:40:00 | |
| 12 | CHP | CC 31 | OLR ACTED | RESET | 19:50:00 | 19:55:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/07/2025

Incharge(s): Amit Roy, K SANKARA RAO

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|-----------------------------------|---|----------------------|----------------------|---|
| 13 | CHP | CC 104 SCR-9 | TUL C/S ACTED | JAMMING CLEANING THAN OK | 20:44:00 | 20:50:00 | |
| 14 | CHP | CC 54 | OLR ACTED (4TIMES) | RESET | 15:15:00 | 19:05:00 | |
| 15 | CHP | CC113A | OLR ACTED | RESET | 18:10:00 | 18:20:00 | |
| 16 | CHP | CC 117 | OLR ACTED | RESET | 19:00:00 | 19:10:00 | |
| 17 | CHP | CC 51 | OLR ACTED | RESET | 21:35:00 | 21:40:00 | |
| 18 | CHP | CC-104 SCR 9 | Reported luff up not taking place | Checked and found rotary cam switch limit acted. Bypassed at I/o rack and luff up tested okay | 18:00:00 | 19:15:00 | Rotary cam switch to be adjusted and to be kept in line |
| 19 | WT | CC 2 (C) DRIVE | OLR ACTED | RESET | 15:30:00 21:15:00 | 15:40:00 21:20:00 | |