



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 09/06/2025

Shift: A

Incharge(s): V Balaji Naik

| Sl No | Area | Equipment                       | Problem  | Action   | From                             | To                               | Remarks |
|-------|------|---------------------------------|--|--|----------------------------------|----------------------------------|---------|
| 1     | OHP  | CO11                            | Over load trip   | Reset done   | 10:10:00                         | 10:15:00                         |         |
| 2     | OHP  | Co11                            | MPCB tripped due to over load trip                               | Reset done   | 07:15:00                         | 07:25:00                         |         |
| 3     | OHP  | TT1A flap gate                  | OLR acted reset done   | Then ok  | 08:00:00                         | 08:45:00                         |         |
| 4     | OHP  | BRC on Co26                     | Slewing not working found drive over load acated                 | Reset done   | 07:30:00                         | 07:45:00                         |         |
| 5     | OHP  | CO9                             | Tripped in over load   | Reset done   | 12:30:00                         | 12:45:00                         |         |
| 6     | CHP  | CC131                           | Over load trip 3 times due to over load                          | Informed operation and reset done  | 07:30:00<br>08:00:00<br>08:15:00 | 07:35:00<br>08:05:00<br>08:20:00 |         |
| 7     | CHP  | CC54                            | Over load acted  | Reset done   | 06:15:00                         | 06:20:00                         |         |
| 8     | CHP  | CC113 TIS                       | Bypassed as per operation request                                | Done   | 13:00:00                         | 13:10:00                         |         |
| 9     | CHP  | CC29                            | TT flap tripped  | Reset done   | 09:20:00                         | 09:30:00                         |         |
| 10    | CHP  | SCR5 on CC32                    | LT not working found MPCB 4 tripped                              | Reset done   | 06:25:00                         | 06:35:00                         |         |
| 11    | CHP  | All machines signal problem CCR | PLC micrologix replaced and IP sddress of PLC micrologix changed | Few mac addresses removed setting in Esteem modem changed to access from all to fixed given mac adresses | 08:30:00<br>13:15:00             | 12:30:00<br>13:30:00             |         |
| 12    | CHP  | R1 on CC31                      | GVM side position not showing in CCR                             | Bypassed in programm and gate way also changed   | 10:30:00                         | 10:45:00                         |         |
| 13    | WT   | OC1a                            | Over load acted  | Reset done   | 09:05:00                         | 09:10:00                         |         |



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 09/06/2025

Incharge(s): V Balaji Naik

Shift: A

| Sl No | Area | Equipment    | Problem   | Action                           | From     | To       | Remarks |
|-------|------|--------------|---|----------------------------------|----------|----------|---------|
| 14    | WT   | OP1          | Not moving in reverse found jamming informed to operation | Breaker tripped in LC 2a made on | 11:30:00 | 11:35:00 |         |
| 15    | WT   | CO4 Carriage | Carriage drive tripped                                    | Reset done                       | 11:00:00 | 11:10:00 |         |