



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 04/06/2025

Incharge(s): Lal Singh, Arnab Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	CHP	CC 36 , SCR 1	Slew left, right, boom position in bypass condition	Found material jamming near limit . Cleaning done, limit healthy and kept in circuit. Boom position bit kept in circuit	06:20:00	06:45:00	
2	CHP	CC 40 , SCR 6	LT not working	Drive reset done . Also material jamming , informed to operation	07:00:00 09:15:00	07:15:00 09:30:00	
3	CHP	CC 39 , SCR 7	BC position missing in GVM side	Bypass removed in IO rack. Then position healthy	07:15:00	07:30:00	
4	CHP	CC 31	Yard stopping frequently due to CC 51 Overload interlock	Overload reset in CC 51	09:05:00	09:30:00	
5	CHP	CC 36 , SCR 1	Slew not working due to left limit acted	Limit released and ok	13:30:00	13:40:00	
6	CHP	CC 111 , S -3	BC signal missing	LT done towards tail end	11:15:00	11:35:00	
7	CHP	CC 54	Tripped on overload	reset done	09:35:00 11:40:00	09:40:00 11:45:00	
8	CHP	CC 131	Tripped on overload	reset done	12:45:00	12:50:00	
9	IOSA	L and T WOBR	LT not working due to limit acted	Limit released	11:00:00	11:15:00	