



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/09/2025

Incharge(s): V Balaji Naik

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|--|--------------------------------------|----------------------|----------------------|---------|
| 1 | OHP | CO29 | olr | reset done | 06:05:00 08:30:00 | 06:10:00 08:35:00 | |
| 2 | OHP | CO26 | olr trip | Reset done | 06:10:00 | 06:15:00 | |
| 3 | OHP | BRC on CO32 | CT not working CT chain came out | Informed to mechanical and operation | 08:10:00 | 08:20:00 | |
| 4 | OHP | BRC on CO33M | BW 1 not working stone struck in ZSS | Removed | 09:30:00 | 09:45:00 | |
| 5 | OHP | Stacker CO21 | chute sensor acting due lake of rubber liners | Reset done | 13:30:00 | 13:40:00 | |
| 6 | CHP | CC26 | Flap gate MPCB trip | Made on | 09:23:00 | 09:35:00 | |
| 7 | CHP | OC1a | ZSS acted due to material jaming | Informed to operation | 10:00:00 | 10:00:00 | |
| 8 | CHP | CC51 | MPD over load trip feeding conveyor stop 5 times | Reset done | 06:50:00 | 06:55:00 | |
| 9 | CHP | SCR3 onCC40 | LT not working drive olr over load trip | Reset done | 07:10:00 | 07:20:00 | |
| 10 | CHP | SCR7 onCC37 | LT not working m5 AND m6 TRIP | mpcb MADE ON | 08:35:00 | 08:45:00 | |
| 11 | CHP | cC125 | OLR TRIP | Reset done | 09:35:00 | 09:45:00 | |
| 12 | CHP | SCR7 onCC37 | BC not running CJB1 2 common not coming | spare core changed | 09:00:00 | 09:20:00 | |
| 13 | CHP | SCR10 on CC105 | chute sensor acted | Reset done cleaned | 12:30:00 | 12:45:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/09/2025

Incharge(s): V Balaji Naik

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|---|--|----------|----------|---------|
| 14 | CHP | SCR1 on CC36 | Position bit not coming | Position bit bypassed GVM | 12:50:00 | 13:00:00 | |
| 15 | CHP | CC44 | motor olr trip | Reset done | 10:00:00 | 10:10:00 | |
| 16 | CHP | CC39 | olr trip | Reset done | 10:50:00 | 10:55:00 | |
| 17 | CHP | SCR7 on CC37 | Slew not working right side limit acted | Limit bypass due to coal jamming informed to operation | 09:45:00 | 09:55:00 | |