



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/06/2025

Incharge(s): Lal Singh, Arnab Roy

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|------------------|--|---|----------------------|----------------------|---------|
| 1 | CHP | CC 36 , SCR 1 | Slew left, right, boom position in bypass condition | Found material jamming near limit . Cleaning done, limit healthy and kept in circuit. Boom position bit kept in circuit | 06:20:00 | 06:45:00 | |
| 2 | CHP | CC 40 , SCR 6 | LT not working | Drive reset done . Also material jamming , informed to operation | 07:00:00 09:15:00 | 07:15:00 09:30:00 | |
| 3 | CHP | CC 39 , SCR 7 | BC position missing in GVM side | Bypass removed in IO rack. Then position healthy | 07:15:00 | 07:30:00 | |
| 4 | CHP | CC 31 | Yard stopping frequently due to CC 51 Overload interlock | Overload reset in CC 51 | 09:05:00 | 09:30:00 | |
| 5 | CHP | CC 36 , SCR 1 | Slew not working due to left limit acted | Limit released and ok | 13:30:00 | 13:40:00 | |
| 6 | CHP | CC 111 , S -3 | BC signal missing | LT done towards tail end | 11:15:00 | 11:35:00 | |
| 7 | CHP | CC 54 | Tripped on overload | reset done | 09:35:00 11:40:00 | 09:40:00 11:45:00 | |
| 8 | CHP | CC 131 | Tripped on overload | reset done | 12:45:00 | 12:50:00 | |
| 9 | IOSA | L and T WOBR | LT not working due to limit acted | Limit released | 11:00:00 | 11:15:00 | |