



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/06/2025

Shift: A

Incharge(s): Lal Singh, Arnab Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|---|---|----------|----------|---------------------------|
| 1 | OHP | CO 35 | OLR acted | reset done | 09:30:00 | 09:40:00 | |
| 2 | OHP | CO 29 | OLR acted | reset done | 09:35:00 | 09:45:00 | |
| 3 | OHP | CO 5 | BRS bypass request from operation | Bypassed AT CJB | 08:00:00 | 08:15:00 | |
| 4 | OHP | SB 2A Bunker | Bunker level to bypass on operation request | bypass done at IO rack | 12:40:00 | 12:55:00 | |
| 5 | OHP | WOBR on CO 6A | LT not taking place due to overtension acted | tension released | 11:25:00 | 11:40:00 | |
| 6 | CHP | CC 131 | Tripped in overload (3 times) | reset done | 07:30:00 | 13:30:00 | |
| 7 | CHP | CC 104 , SCR 9 | OHP side boom position bit not coming | Bypassed in IO rack | 12:30:00 | 12:45:00 | |
| 8 | CHP | CC 35 , SCR 2 | LT not working due to pcrd overtension acted (2 times) | Overtension released | 12:50:00 | 13:25:00 | |
| 9 | CHP | CC 38 , SCR 3 | Luff up to be done due to jamming | bypass done . Again removed | 06:50:00 | 07:05:00 | |
| 10 | CHP | CC 125 | OLR acted | reset done | 13:40:00 | 13:45:00 | |
| 11 | CHP | CC 31 | ZSS probe problem | ZSS bypassed in IO rack | 13:20:00 | 13:30:00 | Probe change job going on |
| 12 | WT | OP 8 | Drive 4 tripped in SL3HF fault | reset done | 09:55:00 | 10:10:00 | |
| 13 | WT | OP 1 | Drive 2 tripping | Motor burn, motor isolated and declutched | 13:30:00 | 13:50:00 | |