



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 03/11/2025

Shift: C

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO-10A	Reported tripped	OLR acted.Reset done	02:50:00	03:00:00	
2	OHP	CO-8	Reported tripped	OLR acted.Reset done	22:20:00	22:30:00	
3	OHP	CO-26	Reported tripped	OLR acted.Reset done	01:35:00	01:45:00	
4	OHP	BRC on CO-8A	Reported CT not moving	Limit stuck up.Released and tested okay	00:45:00	01:15:00	
5	OHP	WOBR on CO-26	Reported slewing not taking place	Drive tripped.Reset done	02:30:00	02:45:00	
6	OHP	BRC on CO-30	Reported B/C not running	OLR acted.Reset done	04:30:00	04:45:00	
7	OHP	BRC on Co-32	Reported both B/W's not running	Hydraulic pump not made on by operator.pump made on and tested okay	23:10:00	23:26:00	
8	CHP	CC51	Reported Tripped	OLR acted(6 times).Reset done	01:00:00	05:25:00	
9	CHP	CC113 A	Reported tripped	OLR acted(3 times).Reset done	22:55:00	00:15:00	
10	CHP	CC54	Reported tripped	OLR acted.Reset done	23:45:00	23:50:00	
11	CHP	Cc-21(C/D)	Reported tripped	MPCB tripped.Made on	22:20:00	22:30:00	
12	CHP	Cc-34 scr-2	Reported slew not taking place	Wrong complaint	22:40:00	22:50:00	
13	CHP	CC107	Reported tripped	OLR acted.Reset done	00:40:00 04:30:00	00:50:00 04:35:00	
14	CHP	CC105 SCR-2	Reported slewing not taking place	30 degree limit acted.Released and tested okay	03:05:00	03:15:00	
15	CHP	CC104 SCR-1	Reported B/W not moving	Wrong complaint	01:08:00	01:16:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 03/11/2025

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
16	WT	CP-4	Communication fault	Reset done	22:35:00	22:40:00	
17	WT	OT-2	Reported initial not coming	Limit switch adjustment done	00:00:00	00:15:00	
18	WT	OP-10	Reported not moving	Drive -2 tripped twice on SCF-3 fault.Bypassed	00:30:00	00:45:00	
19	WT	OP-10	Reported not moving due to wheels slipping	Kept in local and movement done.Drive-4,5 declamp bolts not there.replaced with drive-2 bolts and tested okay.Kept in plc	00:45:00	03:30:00	
20	WT	OT-1	Reported tripped	Drive-1 tripped on PGEF fault.Reset done	05:30:00	05:45:00	
21	WT	OT-3	Reported tripped	Drive-1 tripped on Encoder fault.Reset done	00:20:00	00:35:00	
22	WT	CP-2	Reported not moving	Breaker in off condition.Made on	05:30:00	05:45:00	