



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/11/2025

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|--|---|----------|----------|-----------------|
| 1 | OHP | CO 67 | OLR acted | reset | 05:45:00 | 05:50:00 | |
| 2 | OHP | cO 29 | E PB not released,E push button and P/C fuse blown ,in cjb | fuse replaced,P/C bypassed in CJB | 04:10:00 | 04:30:00 | P/C having e/f, |
| 3 | OHP | CO 29 | OLR acted | reset | 00:10:00 | 00:20:00 | |
| 4 | OHP | TBS on CO 5A | LT not working,M4 tripped continuously | M4 removed | 22:30:00 | 22:40:00 | to be checked |
| 5 | OHP | BRC on Co 28 | b/w 2 working, | b/w 2 chain slipped,informed mechanical | 03:00:00 | 03:10:00 | |
| 6 | CHP | CC 51 | mPD tripped 4 times | reset | 04:45:00 | 05:20:00 | |
| 7 | CHP | CC 52 | mpd tripped | reset | 03:50:00 | 03:55:00 | |
| 8 | CHP | CC 51A | tripped due to jamming | reset | 23:00:00 | 23:05:00 | |
| 9 | CHP | JH 17 | lighting complaint,neutral missing | rectified | 22:30:00 | 22:50:00 | |
| 10 | CHP | CC 40 SCR2 | LT not working,Ot acted | released OT | 00:00:00 | 00:15:00 | |
| 11 | CHP | CC 31 SCR4 | B/W not working,return filter problem | informed mechanical | 00:00:00 | 00:15:00 | |
| 12 | CHP | CC 39 | TUL CS acted | checked found all ok | 00:25:00 | 00:40:00 | |
| 13 | CHP | CC 125 | olr acted | reset | 01:10:00 | 01:15:00 | |
| 14 | CHP | CC 38 SCR6 | LT not working,M2 tripped | reset | 02:15:00 | 02:30:00 | |
| 15 | CHP | CC 40 SCR2 | luff not working,oil level low | informed mechanical | 02:45:00 | 03:00:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/11/2025

Incharge(s): Saurabh Kumar Yadav

Shift: C

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|--|-------------------------|----------|----------|---|
| 16 | CHP | CC 34 SCr1 | LT not working,drive tripped,Ot acted,m5,6,7 OLR acted | reset | 05:20:00 | 05:45:00 | |
| 17 | CHP | CC 105 scr 10 | pcrd cable fallen | PCRD cable winding done | 01:22:00 | 01:35:00 | |
| 18 | IOSA | Oc 19 A | ZSS complaint,probe damaged | probe replaced | 04:45:00 | 05:40:00 | material jamming,operation was cleaning the jamming |