



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/05/2025

Incharge(s):

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|---------------------------------|--|----------------------|----------------------|---|
| 1 | OHP | CO 35 | OLR ACTED | RESET | 17:55:00 | 18:00:00 | |
| 2 | OHP | CO 29 | OLR ACTED | RESET | 18:50:00 | 19:00:00 | |
| 3 | OHP | TT2 ON CO21 | POSITION INDICATION PROBLEM | BY PASSED | 16:00:00 | 16:20:00 | DUE TO SENSOR COVERED WITH JAMMING MATERIAL |
| 4 | CHP | CC 33 , SCR 4 | BC ZSS probe not working | ZSS bypassed in IO rack | 17:40:00 | 17:55:00 | |
| 5 | CHP | CC 32 ,SCR 5 | LT not working | Drive reset | 18:10:00 18:45:00 | 18:20:00 18:55:00 | |
| 6 | CHP | CC 36 , SCR 1 | BC not running due to BSS acted | Belt offcentering , informed to mechanical. After operation request BSS bypassed | 21:00:00 | 21:15:00 | Bypassed in system |