



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/07/2025

Incharge(s): Lal Singh, Arnab Roy

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-------------------|-------------------------------------|--|----------|----------|--------------------|
| 1 | OHP | CO 1A | BRS bypass request | bypassed in CJB | 21:00:00 | 21:10:00 | |
| 2 | OHP | RSCO 10A | CO 15 placement indication missing | wire checked and tightened near switch, CJB . | 16:25:00 | 16:45:00 | |
| 3 | OHP | co-77 | brs kept in ckt as per opr req | done | 21:30:00 | 22:00:00 | |
| 4 | CHP | CC 105 , SCR 7 | Slew not working | Charge pressure alarm . Spider reset | 14:50:00 | 15:15:00 | |
| 5 | CHP | CC 39 | Emergency PB acted | released , then healthy | 17:10:00 | 17:20:00 | |
| 6 | CHP | CC 39 , SCR 6 | BW not running | Oil level low. Informed to mechanical. After mechanical request , oil level low bypassed | 18:00:00 | 20:00:00 | Bypassed in system |
| 7 | CHP | CC 54 | OLR acted (3 times) | reset done | 19:00:00 | 19:30:00 | |
| 8 | CHP | CC 113 | Stopped due to CC 52 overload acted | reset done | 20:20:00 | 20:25:00 | |
| 9 | CHP | CC 26 | Flap gate MPCB tripped | reset done | 16:45:00 | 16:55:00 | |
| 10 | CHP | CC 102 | BRS bypassed on operation request | again kept in circuit | 17:40:00 | 17:50:00 | |