



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/06/2025

Shift: B

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	tbs on co 24	rbc zss acting/return idler got missed	bypassed at module for operation requirement entered in log book	16:30:00	16:50:00	
2	OHP	co 26	tripped on olr	reset done 2times	17:33:00	17:37:00	
3	OHP	brc on co 30	cjd bypassed in A SHIFT	Cjd kept in ckt	14:25:00	14:50:00	
4	OHP	tbs on co 22	chute vibrator not working/olr acted	checked one phase got earthed /insulation done then ok	16:25:00	17:00:00	
5	OHP	co 37a	brs acted/	brs bypassed at module for operation requirement	17:18:00	17:25:00	
6	OHP	wobr on co 6a	luffing not taking place/soloid valve stuckup	manually released then ok	16:36:00	17:00:00	
7	CHP	CC31	Tripped on over load	Reset done	14:25:00 15:20:00	14:30:00 15:25:00	
8	CHP	CC203	Flap gate position 29 side not healthy	Bypassed in panel side	14:50:00	15:00:00	
9	CHP	CC31	Tripped on over current	Reset done	15:15:00	15:20:00	
10	CHP	SCR5 on CC32	LT not working found MPCB 2 and 6 tripped	Reset done	16:05:00	16:15:00	
11	CHP	SCR9 on CC104	SCR9 yard inter lock found healthy	No problem	16:20:00	16:30:00	
12	CHP	SCR1 on CC35	Slewing not working foundMPCB2 tripped	Reset done	16:45:00	16:55:00	
13	CHP	SCR7 on CC39	BW not running found all healthy	Fault reset done then ok	18:05:00	18:15:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/06/2025

Incharge(s): G Eswara Rao

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	SCR5 on CC32	LT not running found MPCB2 tripped	Reset done	19:00:00	19:10:00	
15	CHP	SCR5 on CC32	BC not running found over current acted due to over load on boom conveyor	Fault reset done then ok	20:05:00	20:20:00	
16	CHP	CC53	Pull card switches damaged cable removed and rejoined	Pull cord switches taken in to ckt	14:30:00	15:00:00	
17	CHP	CC117	Motor tripped on over load	Reset done	16:10:00	16:25:00	
18	CHP	CC131	Motor tripped on over load	Reset done	17:00:00	17:05:00	
19	CHP	CC28	TT flap gate tripped	Reset done	17:20:00	17:30:00	
20	CHP	CC114	BRs bypassed as per operational requirement	Bypassed	19:25:00	19:35:00	
21	WT	CC29	Flap gate tripped	reset done	14:20:00	14:30:00	
22	WT	OP9	After rake completion pusher pushed into tippler it went to no power zone (power cut off section)	By providing jumpers pusher brought back to power zone and sent to parking area	21:05:00	21:45:00	