



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/06/2025

Shift: B

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO11	Drive not running found ok	wrong complaint	17:45:00	17:55:00	
2	OHP	CO27A	BRS bypassed as per operational request	By pass removed	19:25:00	19:35:00	
3	OHP	CO84	Belt scle bypassed as per operational request	By passed in IO rake	19:25:00	19:35:00	
4	OHP	TT3 on CO21	Position by passed as per operational request	As per operation arequest	19:25:00	19:35:00	
5	OHP	CO 24	No power found one phase is not coming in LT side checked HT fuses meggared cable from IO panel to slip ring	Checking from Transformer to slip ring and transformer meggaring is under progress	18:30:00	22:30:00	Handed over to C shift
6	CHP	CO8	ZSS cge turned and probe damaged	Probe replaced and cage placed properly Return idler fallen infprmed to mech dept	14:20:00	15:15:00	
7	CHP	Cc131	Over load trip 3 times	Reset done	18:15:00	18:20:00	07.30pm to 07.35pm and 08.15 pm to 08.20pm
8	CHP	Cc54	motor tripped on over load 3 times	Reset done	18:25:00	18:50:00	
9	CHP	CC53	Motor tripped due to over load due to physical load	Informed to operation	16:40:00	16:45:00	
10	CHP	CC40	BRs bypassed	as per operational request and removed	16:55:00	17:00:00	
11	CHP	CC33	DE chte sensor acting without any jam	Chute sensor probe cleaned then ok	17:00:00	17:15:00	
12	CHP	SCR5 on CC32	LT not working found @mtrs tarck jam	Informed to operation for cleaning	18:05:00	18:15:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/06/2025

Shift: B

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	CHP	SCR6 on CC40	LT not working found LT drive trip	Reset done then ok	20:05:00	20:15:00	